ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0430	Nagappa Lyt	G Ramaiah enclave
Segment No.	**Total Length (m)**	
3/S-W0430/S104543	122.85	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	122.85	77.542710	13.093190	77.541605	13.093435	WO761	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing RCC Covering slab to main and cross roads of G Ramaiah enclave in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone	600000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	DRAIN RCC Covering slab
Tender	**Work Details**	**Job No. / Work Code**
Tender	Providing RCC Covering slab to main and cross roads of G Ramaiah enclave in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone	003-17-000034
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D)E-PMT-07/WO/25/2017-18	02/05/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
29/07/2017	28/07/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
VIJAYAKUMAR R		0.00
Phone No.	**E-Mail ID**	
9980022447		

Field Inspection Details

Zone: YELAHANKA	**Ward No:** 3	**Ward Name:** Atturu	**Street ID:** W0430
Date: 12/10/2017	**Time:** 23:06:02	RH20171012230602	

AE-03

Number of Trees	Any Other Information	Name
3		CHANDRAKANTH
Date of Inspection	**Remarks**	
12/10/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0430

Date: 12/10/2017 **Time:** 23:06:02 RH20171012230602

AE-03

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	12/10/2017	11/11/2017	COMPLETED
SE	VASU K M	12/10/2017	11/11/2017	COMPLETED
EE	VASU K M	12/10/2017	11/11/2017	COMPLETED
AEE	ASHOK	12/10/2017	11/11/2017	COMPLETED
AE	CHANDRAKANTH	12/10/2017	11/11/2017	COMPLETED
AE	CHANDRAKANTH	12/10/2017	11/11/2017	COMPLETED

Zone: YELAHANKA Ward No: 3 Ward Name: Alturu Street ID: W0430

Date: 12/10/2017 Time: 23:06:02 RH20171012230602